

OSA - 3789-64

LN 1782

10 August 1964

STATINTL

To:

Fr:

Subject: Service Bulletin HG-SB30

1. Submitted herewith are advance copies of the subject bulletin for your approval for issue.
2. This bulletin is the result of field and shop complaints that film drive clutch torqueys were highly erratic when tested. Investigation showed the erratic readings were due to method of testing and not in the operation of the clutch. The simple device provided for the test stand with this bulletin eliminates this reading error.
3. Parts involved for four kits cost less than \$30.00 per kit and were fabricated on BC-550 rather than the more costly ECP procedure.

STATINTL

AJB:jdj

Encs.